

## JOINT COMPANY-UNION SAFETY COMMITTEE

January 27, 1995

To: [REDACTED]  
HPI  
Building 123  
Ext. [REDACTED]

From: C.W. Buchholz / D.D. Melton  
Joint Company/Union Safety Comm.  
Building T690G / Building T452B  
Ext. 5801 / Ext. 5130

SUBJECT: RESOLUTION OF SAFETY CONCERN 94-058


In response to your safety concern involving, CALIBRATING AND PROCEDURE ISSUES WITH LUDLUM 12-1A, an investigation has been conducted.


A meeting was held to discuss the subject safety concern. R.L. Kennard, Health Physics Instrumentation, recommended three actions to achieve consistency calibrating the LUDLUM Model 12-1A. The JCUSC concurs with these recommendations.

- . To determine the reference value from the attached check source and mark each instrument with the identified value.
- . Label each instrument with the efficiency of the probe used during calibration.
- . A Document Modification Request (DMR), 94-DMR-000893, was written to ROI 6.01/Rev.2 to identify the instruments used for uranium surveys.

Based on the actions described herein, the JCUSC considers this safety concern resolved. Closure will take place pending verification of agreed to corrective actions.

Changes to this agreement cannot be made without concurrence by the JCUSC. If you have additional problems with this concern, the resolution, or the implementation of the corrective action, please contact the JCUSC. Thank you for participating in the safety concern process.

  
C.W. Buchholz  
Union Safety Representative

  
D.D. Melton  
Company Safety Representative

cc:

D.K. Balmer

R.L. Kennard

J.D. Rivera

B.J. Markoff

W.H. Tyree

S.R. Worthington

T.J. Tegeler

E.I. Tietenberg


PATS



JOINT COMPANY - UNION  
SAFETY COMMITTEE

March 10, 1994

TO: [REDACTED]  
HPI  
Building 123  
Ext. [REDACTED]

  
FROM: E. I. Tietenberg / T. J. Tegeler  
Joint Company/Union Safety Committee  
Building T452B / Building T690G  
Ext. 7620 / Ext. 5800

SUBJECT: ASSIGNMENT OF SAFETY CONCERN: 94-058  
CALIBRATING & PROCEDURE ISSUES W/LUDLUM 12-1A

The Joint Company/Union Safety Committee (JCUSC) has received your safety concern and assigned the following investigators. They will contact you to discuss this concern.

Company Representative: D. D. Melton Phone: 5130

Union Representative: C. W. Buchholz Phone: 5801

CC:  
C. W. Buchholz  
J. R. Cable  
W. D. Ewan  
R. L. Kennard  
D. D. Melton  
S. R. Worthington  
PATS

JOINT COMPANY/UNION SAFETY COMMITTEE CONCERN FORM

THIS FORM IS TO BE USED BY ALL EMPLOYEES ON PLANT SITE

Mail to: JCUSC, T-690G

(Please mail Blue Copy to JCUSC when the Concern is initiated)

Case No. 94-058

EMPLOYEE NAME [Redacted] EMPLOYEE NUMBER [Redacted]
DEPARTMENT HPT BLDG. 123 PHONE [Redacted] SHIFT 15T
SUPERVISOR (Print) STEVE WORTHINGTON SUPV. EXT. 2255
MANAGER REPORTING TO DIRECTOR (Print): ROBERT KENNARD MANAGER EXT. 4905

I have previously discussed this Concern with Supervision: [X] Yes [ ] No.

Concern (briefly) (SEE Attached)

Recommendation (Optional)

Employee Signature [Redacted] Date 03-01-94
Steward Signature (If Applicable) Date

Supervision Response (within 5 working days) (Please see attached)

Supervision Signature Steve R. Worthington Date 3-3-94
Manager Reporting to Director R. Kennard Date 3-4-94

NOTE: TIMELINESS IN COMPLETING THIS FORM IS OF THE UTMOST IMPORTANCE.

[ ] I am satisfied with the results. [X] I am not satisfied.

Brief reason if not satisfied: EVALUATIONS AND POSSIBILITIES ARE NOT ADEQUATE SOLUTIONS TO THE ADDRESSED PROBLEMS THAT HAVE BEEN IN EXISTENCE FOR A PERIOD OF TIME - YOU AND OTHER SUPERVISIONS WERE NOTIFIED PRIOR TO FILING OF THIS CONCERN.

Employee Signature [Redacted] Date 03-04-94
JCUSC received Safety Concern on: 3/9/94

To be completed by the JCUSC Co-Chairperson(s)


Assigned to: Union: Buckholz Date 3-9-94
Company: D. Melton Date 3/9/94

- Distribution: Safety Committee (White) (Completed Form)
Union Steward (Yellow)
Employee (Green)
Safety Committee (Blue) (When Concern Initiated)

## INTEROFFICE CORRESPONDENCE

DATE: March 4, 1994

TO: [REDACTED], Health Physics Instrumentation, Bldg. 123, X [REDACTED]

FROM:   
S.R. Worthington, Health Physics Instrumentation, Bldg. 123, X6568

SUBJECT: SUPERVISION RESPONSE TO SAFETY CONCERN -SRW-004-94

Supervision Response (within 5 working days)

I appreciate your concern in filing this Joint Company/Union Safety Committee Concern Form (JCSCCF). However, in the future, if you have any concerns, please give me the opportunity to resolve the problem internally.

The following are CORRECTIVE ACTIONS to be taken to resolve this safety concern.

1. Evaluate the possibility of replacing the Ludlum 12-1As and the Ludlum Model 31s with one instrument that will read both Alpha and Beta.
2. Evaluate the possibility of using one thickness of Mylar for both Black and Green faced Ludlum 12-1As.
3. Evaluate the need to change the Health Physics Instrumentation (HPI), Radiological Operating Instructions (ROI) to provide a better understanding of Uranium Instruments.
4. Evaluate the need to change the tolerance band on efficiency in HPI Procedures.

SRW:srg

CC:  
R. L. Kennard  
T. L. Vaughn

ROCKY FLATS  
RADIOLOGICAL DEFICIENCY REPORT

RDR Number:  
RWP Number:  
Occurrence Reporting Number:

DATE: 2-25-94  
TIME: 1325

LOCATION: (indicate all applicable locations)  
Building 123 Room 133 Building \_\_\_\_\_ Room \_\_\_\_\_  
Building \_\_\_\_\_ Room \_\_\_\_\_ Building \_\_\_\_\_ Room \_\_\_\_\_  
Pad \_\_\_\_\_ Pad \_\_\_\_\_ Pad \_\_\_\_\_ Other \_\_\_\_\_

INDIVIDUALS INVOLVED: [ ] Unknown

Name	Employee No.	Org/Company	Job/Classification	Supervisor
[REDACTED]	[REDACTED]	EG&G	Maintenance	Steve
		Health Physics	Technologist	Worthington
		Instrumentation		

DESCRIPTION OF EVENT: (Check all that apply. If none apply, check "other" and explain)

<input type="checkbox"/> General Area Contamination	<input type="checkbox"/> Wound (confirmed positive)
<input type="checkbox"/> Personnel Contamination (Skin)	<input type="checkbox"/> Failure to Obtain/Adhere to Pre-evolution
<input type="checkbox"/> Company Clothing Contamination	<input type="checkbox"/> Poor Housekeeping in Controlled Area
<input type="checkbox"/> Personal Clothing Contamination	<input type="checkbox"/> Misuse of Respiratory System
<input type="checkbox"/> Contamination in Uncontrolled Area	<input type="checkbox"/> Radiological Posting Violation
<input type="checkbox"/> Spill Contributing to Area Contamination	<input type="checkbox"/> Dosimeter Lost/Not Worn
<input type="checkbox"/> Loss of Radioactive Sources	<input type="checkbox"/> Improper Use of Radiological Containment
<input type="checkbox"/> Improperly Marked Radioactive Material	<input type="checkbox"/> Improper Disposal of Rad Waste
<input type="checkbox"/> Improper or Lacking Radiological Posting	<input type="checkbox"/> Improper Wearing of Anti-C Clothing
<input type="checkbox"/> ALARA Concerns	<input type="checkbox"/> Improper Frisking of Personnel/Items
<input type="checkbox"/> Exceeding Exposure Limits	<input type="checkbox"/> Potential/Confirmed Inhalation Ingestion
<input type="checkbox"/> Exceeding Exposure Administrative Limit	<input type="checkbox"/> Loss of Containment/Control
<input type="checkbox"/> Procedure Violation/Inadequacy	<input checked="" type="checkbox"/> Other RI2000 Calibration of the Ludlum
<input type="checkbox"/> Rad Work Permit Violation/Inadequacy	Model 12-1A count Rate Meter with Air
<input type="checkbox"/> Positive SAAM Alarm w/o Respiratory Protection	Proportional Probe.

DESCRIPTION OF DEFICIENCY: INCLUDE DOCUMENTATION - RWPs, SURVEYS, AIR SAMPLES RESULTS, ETC.  
ANSWER WHO, WHAT, WHEN, WHERE, WHY, AND HOW  
(use additional pages as necessary)

2. 12-1A Count Rate Meter Probe Efficiencies  
3. 12-1A Count Rate Meters used with special use probes.  
4. ROI and RI Procedures dealing with count rate meters.

Please see attached.

IMMEDIATE CORRECTIVE ACTION:

[REDACTED]

DOE 5000.3A, CATEGORIZATION:  Emergency  
 Unusual Occurrence  Off Normal  
 Internally Reportable  
OPS Manager: (if applicable)

REVIEWED: RAD OPS FOREMAN

ORIGINATOR: EMPLOYEE # [REDACTED]	DATE: 2-25-94 TIME: 1330	DATE: TIME:	EMPLOYEE #	DATE: TIME:
--------------------------------------	-----------------------------	----------------	------------	----------------

MANAGER RESPONSIBLE FOR CORRECTIVE ACTION:	TARGET DATE:	RADIOLOGICAL BUILDING ENGINEER	DATE:
		NAME:	TIME:

ACTIONS TAKEN INCLUDING THOSE TO PREVENT RECURRENCE:  
(use additional pages as necessary)

I HAVE CORRECTED THIS RDR AND RECOMMEND CLOSEOUT. DATE: \_\_\_\_\_

RESPONSIBLE MANAGER: \_\_\_\_\_ EMPLOYEE #: \_\_\_\_\_

STATUS:  Satisfactory  Unsatisfactory  Redirected NAME: \_\_\_\_\_

CONCURRENCE: \_\_\_\_\_ EMPLOYEE #: \_\_\_\_\_ DATE: \_\_\_\_\_

APPARENT CAUSE CATEGORY:  Procedures  Communications  Equipment  Training  Personnel  
 Management Systems  Planning  Other \_\_\_\_\_

THIS RDR APPEARS TO HAVE BEEN ADEQUATELY ADDRESSED,  
REQUIRES NO FURTHER ACTION, AND IS CLOSED.

RBE MANAGER: \_\_\_\_\_ DATE: \_\_\_\_\_

2/23/94

The efficiency of the probes used with the Ludlum 12-1A Alpha Count Rate meters has caused wide variances of response on the rate meter drive.

One example is when a Ludlum 12-1A (count rate meter #97563) was submitted for calibration on 1-15-93 as a new instrument. It was calibrated with probe #8412587. Approximately one year later the instrument was returned for calibration (due cal.) with probe #84-1-9496 attached.

As the calibration technologist I found no problem with the high voltage or instrument sensitivity measurements per the electronic portion of RI2000 Procedure. When I got to the as found source portion with probe #84-1-9496 attached to instrument #97563 as it arrived at Bldg. 123 for recalibration I found the internal  $\pm 10\%$  linearity portion to be outside the standard limits. Also, the final reproduction specifications were exceeded on three of 4 final range measurements.

As I understand, the purpose of calibration is to ensure all measurements taken with the Ludlum Count Rate Meter are within  $\pm 20\%$  of the standard. Most 12-1A Count Rate Meters returned for calibration from plutonium operations or used to measure plutonium with the same probe attached as when they were last calibrated meet the requirements RI2000 with no adjustments required for calibration.

I found probes in the field to vary in efficiency's from 6.4% (probe #8413765, 8/18/93) to 8% (probe #8414144, 10/20/92). Variances like this cause the Count Rate Meter to drive meter readings to differences of greater than 20% of the calibration standard for which the 12-1A was set for at calibration. With such probe variances Ludlum 12-1A's are found to be over  $\pm 20\%$  of what the standard states.

Employing the above probes, I ran a comparison. Using the probe with the 6.4% efficiency, I adjusted the rate meter to the  $2\pi$  value of the standard. Then I ran the 8% probe. The results are as follows.

	6.4% Probe #8413765	8% Probe #8414144	
X1K Range	586070 cpm	720000 cpm	=22%
X100 Range	60230 cpm	73000 cpm	=21%
X10 Range	6655 cpm	8200 cpm	=23%
X1 Range	410 cpm	500 cpm	=22%

The ROI Radiological Operational Instructional manual allows for changing of Probes and Performance testing of the changed probe before use in the field of the changed probe.

Considering this problem of which I have attempted to describe, the amount of probe changes & rework that probe & cable

receive and the following problems I feel something in the system is not working well and deserves some looking into.

The ROI does not address the fact that Rocky Flats has 12-1A count rate meters employed in both the plutonium and uranium areas of the plant. These Ludlum 12-1 count rate meters each in their prospective areas use meters identified for use by different color meter faces -ie: green or black. Thinner mylar probes are identified by special markings on the efficiency labels and the screens are identified by a red marking.

Personnel transferred from the plutonium side of the plant to the uranium side of the plant take their instruments with the & vice-versa. This produces false readings right away.

Recently, Ludlum 12-1A Count Rate Meter, SN #73250 (Probe #8417092) was submitted for calibration with an accompanying equipment repair tag that stated this 12-1A count rate meter is (1) over due cal. and (2) has the wrong probe for the instrument. This 12-1A was submitted to Bldg. 123 for calibration from Bldg. 444. From my understanding, Bldg. 444 is a uranium building.


Probe #8417092 is known as a special probe. The efficiency tag is identified with an S on the label. The screen is marked with red markings. This probe's efficiency is of a higher value. meaning, the mylar is thinner than what is employed in non-uranium areas of the plant. The purpose of a thinner mylar allows for increased sensitivity to permit ~~and~~ increased drive to the rate meter.

The reason this meter has the wrong probe attached to it is that Building 444 has meters identified by a green meter face and this meter (SN #73250) has a black meter face indicating it's use in the non-uranium areas.

Radiation Instrumentation procedure RI2000 does not address any such requirements nor does any RI procedure that I know of. The ROI procedure does not address the special probe situation either.

Most of the problems I have addressed here are not in any ROI or RI procedures, but was obtained by word of mouth.

I am available to assist any way I can for more information or clarity.





HEALTH PHYSICS INSTRUMENTATION  
EQUIPMENT DISCREPANCY REPORT

User/Organization: 750 PAD Date/Time: \_\_\_\_\_  
HPI Technician: \_\_\_\_\_ Shop Location: \_\_\_\_\_  
Instrument Serial No.: 97563 Instrument Cal Date: \_\_\_\_\_  
Unit Description: 12-1A ALPHA COUNT RATE METER

- The instrument fails "as found" check.
- The instrument fails a Performance Check.
- The instrument is out of Cal., due date was \_\_\_\_\_
- The instrument fails a Pre-Calibration Performance Check.

AS FOUND ERROR                      NORMAL TOLERANCE

Remarks:

PROBE IS DIFFERENT THAN WHAT HISTORICAL RECORD AT 1-15-93 INDICATES 8412587 ALL AS FOUND RANGES HAD READINGS THAT WERE > (GREATER THAN 20%) OF MEAN READINGS

User Notified Time/Date \_\_\_\_\_

RI Supervision, Time/Date \_\_\_\_\_

Comments:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Disposition:  
\_\_\_\_\_  
\_\_\_\_\_

User Signature, Time/Date \_\_\_\_\_

HPI

RF-47200 (Rev 6/92)

EQUIPMENT REPAIR TAG

☆ U.S. GPO: 1992-676-502

Type/Model: 12-1A Serial # 97563

Identifying: 750 PAD User: Bailey

Date: 1-28-94 Ext./Pager: 8019/

Symptoms of Malfunction:


Cal Due

Unit Free of Contamination by: Truman

Supervisor: Bob Davis Phone: X5677 Date: 1-25-94

Failure Code:

Corrective Action: PROBE WAS CHANGED SINCE  
LAST WAS CALIBRATED. ALL AS FOUND  
READINGS WERE OUT OF TOLERANCE. READJUSTED  
ALL RANGE TO SPECS.  
RECALIBRATED 12-1A

Completed by:  Date: 2-23-94

Historical Record updated by: 

Awaiting Parts:

B 32951

HPI-20001

CALIBRATION DATA SHEET

INSTRUMENT MODEL: Ludlum Model 12-1A with Air Proportional Probe CAL START TIME: 7:46  
 LAST CAL DATE: 1-15-93 MFG SERIAL NO.: 97563  
 CAL DATE: 2-23-94 CAL FREQ: 1 year 6 mos NEXT CAL DUE DATE: 8-94  
 ALL LIN'S COMPLETED (YES) (Y/N)

TEST EQUIPMENT DESCRIPTION	STD LAB NO	CAL DUE DATE	CSI SOURCE NO	DUE DATE	VALUE (DPM)
<u>PULSER</u>	<u>92771</u>	<u>4-94</u>	<u>1) 603559</u>	<u>12-94</u>	<u>921</u>
<u>WATCH</u>	<u>85990</u>	<u>6-94</u>	<u>2) 603560</u>		<u>13310</u>
<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>3) 603561</u>		<u>120460</u>
<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>4) 603562</u>	<u>↓</u>	<u>1173147</u>

PRECALIBRATION:

6.1.6 BATTERIES: CHECKED ✓ REPLACED ✓ PASS: ✓ FAIL:      
 6.1.11 ZERO CHECK ✓ Zero Draft  $\leq 1/2$  of a minor division PASS: ✓ FAIL:      
 6.1.13 GEOTROPISM CHECK Needle movement  $\leq 1$  minor division PASS: ✓ FAIL:      
 6.4.4.14 ENVIRONMENT: Temp: 76.4 Humidity: 14.8 Baro Pres: 608.0  
 6.4.4.15 Probe Serial Number: 8419496

REPRODUCIBILITY TEST

6.2.4 Reading 1) 76000  
 Reading 2) 75000  
 Reading 3) 75000  
 6.2.7 AVG 75333  
 6.2.7 +10% 82966 Acceptance Criteria reading 1, 2, & 3 are between  $\pm 10\%$  of Average Response  
 6.2.8 -10% 67799 PASS ✓ FAIL    

HIGH VOLTAGE:

6.3.3 Acceptance Criteria (1840  $\pm$  10 VDC)  
 AS FOUND 1842 (VDC)  
 AS LEFT 1842 (VDC)  
 PASS ✓ FAIL    

SENSITIVITY:

6.4.12 AUDIO CHECK (HEADPHONES) Acceptance Criteria (2.75  $\pm$  .25 mV) Able to hear pulses  
 PASS ✓ FAIL      
 PASS ✓ FAIL    

RESPONSE TIME:

6.5.5 Fast Response Time 4:41 4  $\pm$  1 Sec PASS ✓ FAIL      
 6.5.10 Slow Response Time 23:63 22  $\pm$  4 Sec PASS ✓ FAIL    

TRIP CALIBRATION			
J	CAL DATE	SERIAL NO.	
A	<u>1-15-93</u>	<u>97563</u>	
N	DUE DATE	SOURCE	
	<u>1-94</u>	<u>Pu-239</u>	
	BY	TOLERANCE	
	<u>514481</u>	<u><math>\pm 20\%</math></u>	

ATTACHMENT 9.2 CONT.

NEARITY:

6.6.4	As Found	1K Reading: <u>690 000</u>	
6.6.7	As Left	1K Reading: <u>586 070</u> ( $2\pi$ value of source $\pm 10\%$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.10	As Found	100 Reading: <u>90 000</u>	
6.6.13	As Left	100 Reading: <u>60 230</u> ( $2\pi$ value of source $\pm 10\%$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.17	As Found	10 Reading: <u>85 00</u>	
6.6.20	As Left	10 Reading: <u>655</u> ( $2\pi$ value of source $\pm 10\%$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.30	As Found	1 Reading: <u>700</u>	
6.6.321	As Left	1 Reading: <u>500</u> ( $500 \pm 50$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.34		Meter Reading: <u>250</u> ( $250 \pm 25$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.36		Meter Reading: <u>750</u> ( $750 \pm 75$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.40		Meter Reading: <u>250</u> ( $250 \pm 25$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.42		Meter Reading: <u>750</u> ( $750 \pm 75$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.46		Meter Reading: <u>250</u> ( $250 \pm 25$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.48		Meter Reading: <u>750</u> ( $750 \pm 75$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.52		Meter Reading: <u>250</u> ( $250 \pm 25$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.54		Meter Reading: <u>750</u> ( $750 \pm 75$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>
6.6.59	As Found	Meter Reading: <u>425</u>	
6.6.61	As Left	Meter Reading: <u>410</u> ( $2\pi$ value of source $\pm 10\%$ )	PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>

REPRODUCIBILITY TEST

6.7.4	Reading 1) <u>60000</u>
	Reading 2) <u>60000</u>
6.7.7	Reading 3) <u>60000</u>
	AVG <u>60000</u>
6.7.7	+10% <u>66000</u>
6.7.8	-10% <u>54000</u>

Acceptance Criteria reading 1, 2, & 3 are between  $\pm 10\%$  of Average Response

PASS  FAIL

COMMENTS: PROBE CHANGED SINCE LAST CAL. - ALL AS FOUND READINGS OUT OF TOLERANCE SINCE LAST CAL. All Adj. TO SPECS WHEN CALIBRATED

CAL SAT: YES  NO  CAL STOP TIME: 12 27  
 CAL BY: HERBERT J. WEINERT  
 Print \_\_\_\_\_ Signature \_\_\_\_\_

DATE: 2-23-94

SUPERVISOR REVIEW: \_\_\_\_\_  
 Signature \_\_\_\_\_

DATE: \_\_\_\_\_

QA REVIEW (OPTIONAL): \_\_\_\_\_  
 Signature \_\_\_\_\_

DATE: \_\_\_\_\_

EQUIPMENT HISTORICAL RECORD  
Radiation Instrumentation

NOMENCLATURE: Count rate meter  
 MANUFACTURE: Lucium  
 CALIBRATION INTERVAL: 1 year 6 mos

TYPE/MODE: 12-1A  
 INITIAL ACCEPTANCE DATE: 1-15-93  
 CALIBRATION REQMS: RT-2000

SERIAL #: 97563  
 BUILDING: 750 PAD

DATE DESCRIPTION OF WORK

ACTIVITY PERFORMED

PARTS USED

EMP. #

DATE	DESCRIPTION OF WORK	ACTIVITY PERFORMED	PARTS USED	EMP. #
15-93	Acceptance test	cal'd replaced C163	1012LF cap	514481
23-94	DYE CAL	RECALIBRATED		510547

Type/Model: 1111111111 Serial # 475603

Building: \_\_\_\_\_ User/Tech: \_\_\_\_\_

Date: 11/13/92 Org: \_\_\_\_\_

Symptoms of Malfunction:

Fluctuating H.V.  
Acceptance cal

DATA  
ENTERED

Unit Free of Contamination By: \_\_\_\_\_

Supervisor: \_\_\_\_\_ Phone: \_\_\_\_\_ Date: \_\_\_\_\_

Corrective Action: (If AWP-list Parts Below)

Modified H.V. per Ludlum  
.001 → .01 of CAP.

CO2/12-1A

514481 1-15-93

G. [Signature] (518556) 11.13.92  
Completed by: (Emp. #) Date

Awaiting Parts:

ORDER

Part#	Noun	Qty	Date	By
1				
2				
3				

Supervisors Review: \_\_\_\_\_ Date: \_\_\_\_\_

R 10A55

ATTACHMENT 9.2

CALIBRATION DATA SHEET

DATA ENTERED

INSTRUMENT MODEL: Ludlum Model 12-1A with Air Proportional Probe CAL START TIME: 0900  
 LAST CAL DATE: New MFG SERIAL NO.: 97563  
 CAL DATE: 1-15-93 CAL FREQ: 1 year NEXT CAL DUE DATE: 1-94  
 ALL LIN'S COMPLETED: yes (Y/N)

TEST EQUIPMENT DESCRIPTION	STD LAB NO	CAL DUE DATE	CSL SOURCE NO	DUE DATE	VALUE (DPM)
<u>Pulser</u>	<u>RF91242</u>	<u>3/93</u>	<u>1) 603547</u>	<u>10/93</u>	<u>1100</u>
<u>Stopwatch</u>	<u>RF95990</u>	<u>6/93</u>	<u>2) 603548</u>	<u>10/93</u>	<u>13190</u>
			<u>3) 603549</u>	<u>10/93</u>	<u>123000</u>
			<u>4) 603550</u>	<u>10/93</u>	<u>121000</u>

PRECALIBRATION:

6.1.6 BATTERIES: CHECKED  REPLACED  PASS:  FAIL:   
 6.1.11 ZERO CHECK  Zero Draft  $\leq$  1/2 of a minor division PASS:  FAIL:   
 6.1.13 GEOTROPISM CHECK Needle movement  $\leq$  1 minor division PASS:  FAIL:   
 6.4.4.14 ENVIRONMENT: Temp: 84.7°F Humidity: 13.4% Baro Pres: 608.4 mm Hg  
 6.4.4.15 Probe Serial Number: 8Y12587

REPRODUCIBILITY TEST

6.2.4 Reading 1) N/A  
 Reading 2) N/A  
 Reading 3) N/A  
 6.2.7 AVG N/A  
 6.2.7 +10% N/A  
 6.2.8 -10% N/A  
 Acceptance Criteria reading 1, 2, & 3 are between  $\pm$  10% of Average Response  
 PASS N/A FAIL N/A

HIGH VOLTAGE:

6.3.3 Acceptance Criteria (1840  $\pm$  10 VDC)  
 AS FOUND NA (VDC)  
 AS LEFT 1840 (VDC)  
 PASS  FAIL

SENSITIVITY:

6.4.12 AUDIO CHECK (HEADPHONES) Acceptance Criteria (2.75  $\pm$  .25 mV) Able to hear pulses  
 PASS  FAIL   
 PASS  FAIL

RESPONSE TIME:

6.5.6 Fast Response Time 2.77  $4 \pm 1$  Sec PASS  FAIL   
 6.5.10 Slow Response Time 18.35  $22 \pm 4$  Sec PASS  FAIL

**ATTACHMENT 9.2 CONT.**

**LINEARITY:**

6.6.4	As Found	1K Reading: <u>N/A</u>	
6.6.7	As Left	1K Reading: <u>600K</u> (2 $\pi$ value of source $\pm$ 10 %)	PASS <u>X</u> FAIL _____
6.6.10	As Found	100 Reading: <u>N/A</u>	
6.6.13	As Left	100 Reading: <u>62500</u> (2 $\pi$ value of source $\pm$ 10 %)	PASS <u>X</u> FAIL _____
6.6.17	As Found	10 Reading: <u>N/A</u>	
6.6.20	As Left	10 Reading: <u>6500</u> (2 $\pi$ value of source $\pm$ 10 %)	PASS <u>X</u> FAIL _____
6.6.30	As Found	1 Reading: <u>N/A</u>	
6.6.321	As Left	1 Reading: <u>500</u> (500 $\pm$ 50)	PASS <u>X</u> FAIL _____
6.6.34		Meter Reading: <u>250</u> (250 $\pm$ 25)	PASS <u>X</u> FAIL _____
6.6.35		Meter Reading: <u>750</u> (750 $\pm$ 75)	PASS <u>X</u> FAIL _____
6.6.40		Meter Reading: <u>250</u> (250 $\pm$ 25)	PASS <u>X</u> FAIL _____
6.6.42		Meter Reading: <u>750</u> (750 $\pm$ 75)	PASS <u>X</u> FAIL _____
6.6.46		Meter Reading: <u>250</u> (250 $\pm$ 25)	PASS <u>X</u> FAIL _____
6.6.48		Meter Reading: <u>750</u> (750 $\pm$ 75)	PASS <u>X</u> FAIL _____
6.6.52		Meter Reading: <u>250</u> (250 $\pm$ 25)	PASS <u>X</u> FAIL _____
6.6.54		Meter Reading: <u>750</u> (750 $\pm$ 75)	PASS <u>X</u> FAIL _____
6.6.59	As Found	Meter Reading: <u>N/A</u>	
6.6.61	As Left	Meter Reading: <u>550</u> (2 $\pi$ value of source $\pm$ 10 %)	PASS <u>X</u> FAIL _____

**REPRODUCIBILITY TEST**

6.7.4	Reading 1) <u>62500</u>	
	Reading 2) <u>62500</u>	
	Reading 3) <u>62500</u>	
6.7.7	AVG <u>62500</u>	
6.7.7	+10% <u>68750</u>	Acceptance Criteria reading 1, 2, & 3 are between $\pm$ 10% of Average Response
6.7.8	-10% <u>56250</u>	
		PASS <u>X</u> FAIL _____

COMMENTS: Post cal. Temp 85.4°F Humidity 13.2% Pressure 603.8 mm Hg  
CO2/12-1A

CAL SAT: YES X NO \_\_\_\_\_ CAL STOP TIME: 0945  
 CAL BY: Richard Dolpizzo Richard Dolpizzo DATE: 1-15-93  
 Print Signature  
 SUPERVISOR REVIEW: [Signature] DATE: 1-16-93  
 Signature  
 QA REVIEW (OPTIONAL): \_\_\_\_\_ DATE: \_\_\_\_\_  
 Signature

3





1F-17200 (Rev 6/92)

# EQUIPMENT REPAIR TAG

☆ U.S. GPO: 1992-676-502

Type/Model: 12-1A Serial # 73250

Building: 444 User: \_\_\_\_\_

Date: 2-10-94 Ext./Pager: \_\_\_\_\_

Symptoms of Malfunction:

Over Due Cal  
wrong probe for instr.

Unit Free of Contamination by: Denis Brewer

Supervisor: Bob Davis Phone: 5677 Date: 2-10-94

Failure Code: \_\_\_\_\_

Corrective Action: ATTACHED PROBZ HOLDER HTW

Completed by: \_\_\_\_\_  
Signature & Employee Number Date

Historical Record updated by: \_\_\_\_\_

Awaiting Parts:

B 32972

# HEALTH PHYSICS INSTRUMENTATION EQUIPMENT DISCREPANCY REPORT

User/Organization: 444  
 HPI Technician: [REDACTED] Date/Time: 2-23-94 1354  
 Instrument Serial No.: 13550 Shop Location: B3  
 Unit Description: LUDLUM 12-1A COUNT RATE METER Instrument Cal Date: \_\_\_\_\_

- The instrument fails "as found" check.
- The instrument fails a Performance Check.
- The instrument is out of Cal., due date was \_\_\_\_\_
- The instrument fails a Pre-Calibration Performance Check.

AS FOUND ERROR                      NORMAL TOLERANCE

*T on Hold  
K. Howe*

Remarks: ATTACHED PROBE HOLDER, N/W (ATTACHED REVISION LABEL)  
PROBE # 84-11-3053 WHEN SUBMITTED FOR CAL ON 2-10-94  
PROBE # 84-1-7092 WAS ATTACHED TO INSTRUMENT.  
FOUND HOLD IN PROBE - NOT SCREEN WHICH WAS  
FOUND WITH FACE DOWN      RED MARKED SCREEN CASE NOT  
GO WITH BLACK FACED TRIST.

User Notified Time/Date \_\_\_\_\_

RI Supervision, Time/Date \_\_\_\_\_

Comments:  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Disposition:  
 \_\_\_\_\_  
 \_\_\_\_\_

User Signature, Time/Date \_\_\_\_\_

EQUIPMENT HISTORICAL RECORD  
Radiation Instrumentation

NOMENCLATURE: Count RATEMETER  
 MANUFACTURE: LUDLUM  
 CALIBRATION INTERVAL: 1YR  
 DATE \_\_\_\_\_  
 DESCRIPTION OF WORK \_\_\_\_\_

TYPE/MODE: 12-1A  
 INITIAL ACCEPTANCE DATE: 4-14-90  
 CALIBRATION REQMS: RI-2000  
 ACTIVITY PERFORMED \_\_\_\_\_

SERIAL #: 73250  
 BUILDING: 123

4-14-90	ACCEPTANCE TEST	INITIAL CALY, INSTALLED SADDLE	ISA00LE PROBE HOLDER	514909
4-19-90	Temporarily ass. std to Bldg. 444	for training		
1/11/93	Due cal	calibration	N/A	S17971

11



## JOINT COMPANY-UNION SAFETY COMMITTEE

Date: March 15, 1994

To: Distribution

From: <sup>CWB</sup> C. W. Buchholz, Joint Company/Union Safety Committee,  
Building T690G, Ext. 5801  
<sup>D.M.</sup> D. D. Melton, Joint Company/Union Safety Committee,  
Building T881B, Ext. 5130

**SUBJECT: REQUEST FOR PARTICIPATION IN SAFETY CONCERN PROCESS:  
94-058**

██████████ has filed a safety concern with the Joint Company/Union Safety Committee (JCUSC). The responsibility for resolving safety concerns lies with line management.

The JCUSC requests participation from you or your designated representative in resolving this safety concern. Please bring all documentation that you have in regards to this issue to this meeting. The meeting to determine a course of action for this concern has been set for the following:

Date: March 29, 1994

Time: 09:00 AM

Location: T690G Conference Room

Please contact C.W.Buchholz or D.D.Melton to confirm your attendance at this meeting.

The JCUSC appreciates your participation in the safety concern process.

**DISTRIBUTION:**

██████████  
R.L. Kennard

J.D. Rivera

T.L. Vaughn

S.R. Worthington

ADD  
W. TYREE

CONCERN NUMBER 94-058

BRIEF DESCRIPTION PROCEDURES AND CALIBRATION OF LUDHUM 12-1A

DATE ~~5-16-94~~ 5-16-94

MEETING PLACE T690G

JOINT COMPANY UNION SAFETY COMMITTEE REPS. C. BUCHHOLZ  
D. D. MELTON

ATTENDANCE LIST

NAME	GROUP	BLDG.	PHONE	PAGE
DK Balmer	RDE	441	2670	0646
RL Kennard	HPI	790	4805	7001
J.D. Rivera	LHS	T-690-C	2177	1636
W.H. Tyree	HPI	123	7777	0896
R. Worthington	HPI	123	6568	7007



USWA



# JOINT COMPANY - UNION SAFETY COMMITTEE

DATE: \_\_\_\_\_

TO: \_\_\_\_\_

FROM: \_\_\_\_\_

Bldg. \_\_\_\_\_  
Ext. \_\_\_\_\_

Bldg. \_\_\_\_\_ \ Bldg. \_\_\_\_\_  
Ext. \_\_\_\_\_ \ Ext. \_\_\_\_\_

SUBJECT: RESOLUTION OF SAFETY CONCERN:  
TITLE \_\_\_\_\_ BLDG. \_\_\_\_\_

The Joint Company/Union Safety Committee (JCUSC) has investigated the subject safety concern, and the results of this investigation are as follows:

(Describe actions taken to resolve concern)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Based on the actions described herein, the JCUSC considers this safety concern resolved. Closure will take place pending verification of agreed to corrective actions.

Changes to this agreement cannot be made without concurrence by the JCUSC. If you have additional problems with this concern, the resolution, or the implementation of the corrective actions, please contact the JCUSC. Thank you for participating in the safety concern process.

\_\_\_\_\_  
Company Safety Representative

\_\_\_\_\_  
Union Safety Representative

cc:

T. J. Tegeler  
E. I. Tietenberg

CAL. WAS 25% OFF / TOLERANCE 6.4% - 8%  
DIFFERENCE IS  $\Rightarrow$  22% / URANIUM PROBE /  
SOURCE BOARD 20K + DIFFERENCE (TOP)

RCT'S PERFORMANCE TEST INSTRUMENT AFTER CHANGING  
PROBE / SOURCE BOARDS MAY BE DRIFTING / RE-CERT TO  
VERIFY / PROBE WITH ONLY 1% WINDOWS  
Pu 6.5% - 7.5% U 8.5% - 9.5%

TRAINING / ADD <sup>EFT</sup> PERCENTAGE THAT PROBE  
WAS CALIBRATED WILL BE ADDED TO CAL.

STRICKER / SOURCE BOARD ? / D. MR. /

DMR / ~~R. D. STICKER~~

R. KENNARD — 5-23-94 /  
5-23-94 / S. R. WORTHINGTON

MORRISSEY



## JOINT COMPANY-UNION SAFETY COMMITTEE

Date: May 5, 1994

To: Distribution

From: *ve* W. Buchholz, Joint Company/Union Safety Committee,  
Building T690G, Ext. 5801  
D. D. Melton, Joint Company/Union Safety Committee,  
Building T881B, Ext. 5130

SUBJECT: REQUEST FOR PARTICIPATION IN SAFETY CONCERN PROCESS:  
94-058

██████████ has filed a safety concern with the Joint Company/Union Safety Committee (JCUSC). The responsibility for resolving safety concerns lies with line management.

The JCUSC requests participation from you or your designated representative in resolving this safety concern. Please bring all documentation that you have in regards to this issue to this meeting. The meeting to determine a course of action for this concern has been set for the following:

Date: May 16, 1994

Time: 09:00 AM

Location: T690G Conference Room

Please contact C.W.Buchholz or D.D.Melton to confirm your attendance at this meeting.

The JCUSC appreciates your participation in the safety concern process.

DISTRIBUTION:

A.J. Asti

H.J. Weinert

R.L. Kennard

J.D. Rivera

T.H. Tyree

T.L. Vaughn

S.R. Worthington



6. INSTRUCTIONS- CALIBRATION OF LUDLUM MODEL 12-1A

6.1 Pre-calibration

Health Physics Instrumentation Technician

- [1] Verify and document on Appendix 1, Calibration Data Sheet, hereinafter called the "Data Sheet", that all prerequisites in Section 5 are complete.
- [2] Enter the Calibration Start Time/Date, Manufacturer's Serial Number, Calibration Frequency, Previous Calibration Date, Current Calibration Date, and Next Calibration Due Date on the Calibration Data Sheet.
- [3] Verify all Logic Improvement Notices (LIN) have been completed per 4-61200-HPI-0008, Logic Improvement System Users Guide and document on the Calibration Data Sheet.
- [4] IF all LINs have not been completed,  
THEN submit instrument for LIN installation.
- [5] Record the Test Equipment Description, Chemical Standards Lab (CSL) Number, and Calibration Due Date on the Data Sheet for each piece of calibrated test equipment used (see Section 5).
- [6] Record the CSL Source Serial numbers, the Source Calibration Due Dates, and the CSL Source Values in dpm for each source on the Data Sheet.

NOTE Ludlum Model 12-1A instruments with the green meter faces are for use in uranium areas only. These instruments require special uranium probes which are distinguished by the words "~~SPECIAL~~ URANIUM USE ONLY" on the Efficiency Tag and green markings on the screen. <sup>in Green Ink.</sup> Report any out-of-compliance instruments to Health Physics Instrumentation supervision.

- [7] Visually inspect instrument, cable, probe, mylar and screen holder for obvious damage before calibration is sta

5/13/94

Post-It™ brand fax transmittal memo 7671 # of pages ▶ 1

To Steve Worthington	From Bob Stevens
Co. X6548	Co. X7219
Dept. Rad. Instr.	Phone # Rad Eng.
Fax # 2954	Fax # 8459

5/13/94

Post-It™ brand fax transmittal memo 7671 # of pages ▶ 2

To	Steve Worthington	From	Bob Stevens
Co.	X 6568	Co.	X 7219
Dept.	Rad. Instr.	Phone #	Rad Eng.
Fax #	2954	Fax #	8459

6.0 INSTRUCTION

6.1 Precalibration

- 6.1.1 Obtain a copy of the Calibration Data Sheet (see Attachment 9.2). Enter the Manufacturer's Serial Number on the Calibration Data Sheet. Verify all LINS have been completed and document on the Calibration Data Sheet. If not submit instrument for LIN installation.
- 6.1.2 Enter the current Calibration Date, Previous Calibration Date, Start Time, and the Next Calibration Due Date on the Calibration Data Sheet.
- 6.1.3 Record the Test Equipment description, Chemical Standards Lab (CSL) number, and calibration due date on the Calibration Data Sheet for each piece of calibrated test equipment used. Verify the current calibration for each item.
- 6.1.4 Record the Calibration Source serial numbers, the source calibration due dates, and the CSL Standard Source Values in DPM for each source on the Calibration Data Sheet. Verify the current calibration for each source.
- 6.1.5 Visually inspect the instrument, cable, and probe for damage. Closely inspect for mylar damage or a bent screen holder. If the screen holder is damaged, replace the screen holder with a standard shop screen holder during calibration.

**NOTE**

Ludlum Model 12-1A instruments with the green meter faces are for use in uranium areas only. These instruments require special uranium probes which are distinguished by the words "SPECIAL URANIUM USE ONLY" on the Efficiency Tag and green markings on the screen. Report any out-of-compliance instruments to Health Physics Instrumentation supervision.

- 6.1.6 Place the range selector switch in the BAT position. The meter should deflect into the Bat. Test range. Replace batteries as necessary. Document satisfactory battery test on the Calibration Data Sheet.
- 6.1.7 Place the instrument range selector switch in the OFF position.
- 6.1.8 Remove the old Calibration Tag from the Ludlum 12-1A.
- 6.1.9 If necessary, adjust the meter mechanical zero for a meter reading of zero by adjusting the screw on the meter face. Minimize parallax errors by viewing from directly overhead. If meter cannot be adjusted, maintenance is required.

- 6.1.10 Place the range selector switch in the X10 position. Allow a warmup time of at least one minute.
- 6.1.11 Verify that zero drift does not cause the meter to indicate more than one half a minor division from zero. Document satisfactory zero check on the Calibration Data Sheet. Failure of the zero drift check requires maintenance.
- 6.1.12 Geotropism check is performed by holding the handle of the instrument at arm's length with the meter face in a vertical plane and rotating the instrument to the 90 degree, 180 degree, 270 degree, and 360 degree positions.

DRAFT

January 27, 1995

To: [REDACTED]  
HPI  
Building 123  
Ext. [REDACTED]

From: C.W. Buchholz / D.D. Melton  
Joint Company/Union Safety Comm.  
Building T690G / Building T452B  
Ext. 5801 / Ext. 3057

SUBJECT: RESOLUTION OF SAFETY CONCERN 94-058

In response to your safety concern involving, CALIBRATING AND PROCEDURE ISSUES WITH LUDLUM 12-1A, an investigation has been conducted.

A meeting was held to discuss the subject safety concern. R.L. Kennard, Health Physics Instrumentation, recommended three actions to achieve consistency calibrating the LUDLUM Model 12-1A. The JCUSC concurs with these recommendations.

- . To determine the reference value from the attached check source and mark each instrument with the identified value.
- . Label each instrument with the efficiency of the probe used during calibration.
- . A Document Modification Request (DMR), 94-DMR-000893, was written to ROI 6.01/Rev.2 to identify the instruments used for uranium surveys.

Based on the actions described herein, the JCUSC considers this safety concern resolved. Closure will take place pending verification of agreed to corrective actions.

Changes to this agreement cannot be made without concurrence by the JCUSC. If you have additional problems with this concern, the resolution, or the implementation of the corrective action, please contact the JCUSC. Thank you for participating in the safety concern process.

DRAFT

C.W. Buchholz  
Union Safety Representative

D.D. Melton  
Company Safety Representative

cc:

D.K. Balmer

R.L. Kennard

J.D. Rivera

B.J. Markoff

W.H. Tyree

S.R. Worthington

T.J. Tegeler

E.I. Tietenberg

PATS

DRAFT



EG&G ROCKY FLATS, INC.  
ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORADO 80402-0464 • (303) 966-7000

May 26, 1994

94-RF-05936

Delmar D. Melton  
Joint Company Union Safety Committee  
Building T452B

RESOLUTION TO SAFETY CONCERN #94-058 - RLK-057-94

This letter is to confirm the acceptance of corrective actions to be taken by my organization to resolve this safety concern.

Action Number 1: To determine the reference value from the attached check source and mark each instrument with the identified value.

Resolution: This will be accomplished on each Ludlum 12-1A instrument during the next calibration.

Completion Date: May 1, 1995

Action Number 2: Label each instrument with the efficiency of the probe used during calibration.

Resolution: This will be accomplished on each Ludlum 12-1A instrument during the next calibration.

Completion Date: May 1, 1995

If you have any questions regarding this issue, please contact me at Extension 4905.

A handwritten signature in cursive script, appearing to read 'R. L. Kennard'.

R. L. Kennard  
Manager  
Health Physics Instrumentation

cmk

## FAX TRANSMITTAL MEMO

May 13, 1994	3 page(s) total
To Steve Worthington	From Erik von Hortenau
Health Physics Instrumentation	Radiological Engineering
Building 123	Building T-690A
Fax: 2954	Fax: 8459
Phone: 7568	Phone: 8455

DOCUMENT MODIFICATION REQUEST (DMR)

Refer to 1-A01-PPG-001 for Processing Instructions.  
Print or Type All Information (Except Signatures).

1. Date April 5, 1994	26. DMR No. 94-DMR-000893
--------------------------	------------------------------

2. Existing Document Number/Revision ROI 6.01 / Rev. 2	3. New Document Number or Document Number if it is to be changed with this revision N/A
---	--

4. Originator's Name/Phone/Pager/Location G. C. Becker / X2255 / D1522 / 123	5. Document Title Performance Test and Operational Checks for Ludlum Models 12-1A and 31 Survey Instruments
---	--

6. Document Type <input checked="" type="checkbox"/> Procedure <input type="checkbox"/> Other	7. Document Modification Type (Check only one) <input type="checkbox"/> New <input type="checkbox"/> Revision <input checked="" type="checkbox"/> Intent Change <input type="checkbox"/> Nonintent Change <input type="checkbox"/> Editorial Correction <input type="checkbox"/> Cancellation
---	--

8. Item	9. Page	10. Step	11. Proposed Modifications
1	3	5.3	Insert the following note: <i>NOTE: Ludlum Model 12-1A instruments with green meter faces are for use in uranium areas only. These instruments require special uranium probes which are distinguished by the words "URANIUM USE ONLY" stamped in green ink on the Efficiency Tag and on the screen.</i>
2	3	5.3	Insert the following new Step 5.3: <i>Notify Radiological Operations Foreman whenever finding a Ludlum Model 12-1A instrument or probe which is incorrect for the given area and renumber remaining steps in Section 5 as required.</i>

12. Justification (Reason for Modification, EJO #, TP #, etc.)  
Change is required to answer Safety Concern 94-058 which resulted from finding uranium instruments with regular probes attached and regular instruments with special uranium probes attached.

If modification is for a new procedure or a revision, list concurring disciplines in Block 13, and enter N/A in Blocks 14 and 15. If modification is for any other type of change or a cancellation, organizations are listed in Block 13, and then Concurror prints, and signs in Block 14, and dates in Block 15.

13. Organization	14. Print, Sign (if applicable)	15. Date (if applicable)
H&S AM	/s/ J. Kokot	4/11/94
Orig.	/s/ C. Becker	4/7/94
SQA	/s/ J. E. Hoff	4/13/94
SME	/s/ K. S. Kent	4/7/94
RO T&C	/s/ P. A. Dukart	5/4/94

16. Originator's Supervisor (print, sign, date)  
S. R. Worthington *S. R. Worthington* 5-5-94

17. Assigned SME/Phone/Pager/Location G. C. Becker / X2255 / D1522 / 123	18. Cost Center 0409	19. Charge Number 82403900	20. Requested Completion Date 5-15-94	21. Effective Date 5-9-94
---	-------------------------	-------------------------------	--	------------------------------

22. Accelerates Review? Yes  No   
23. ORC Review  
ORC review not required

24. Responsible Manager (print, sign, date)  
J. M. Wood *J. M. Wood* 5/5/94

REVIEWED FOR CLASSIFICATION/UCNI  
BY *[Signature]*



RADIOLOGICAL OPERATING INSTRUCTIONS  
Performance Test and Operational Checks for Ludlum  
Models 12-1A and 31 Survey Instruments

ROI 6.01, Rev. 2  
Page 3 of 13  
June 27, 1991

- 5.2 If Radiological Operations is informed by Health Physics Instrumentation (HPI, formerly Radiation Instrumentation - RI) that an instrument has failed calibration, The RP Foreman shall take the following actions:
- 5.2.1 Verify whether instrument was used since last satisfactory performance check. If not, provide appropriate remarks on HPI Equipment Discrepancy Report.
  - 5.2.2 If instrument was used, review surveys in question from the suspect instrument and evaluate whether or not the data appears reasonable. If data appears reasonable, provide appropriate remarks on HPI Equipment Discrepancy Report.
  - 5.2.3 If irregularities exist between historical data and data obtained, the RP Foreman shall resurvey all areas which may have questionable data, or justify actions, and initiate a RDR in accordance with ROI 10.01 (Reference 7.3).

NOTE

*Ludlum Model 12-1A instruments with green meter faces are for use in uranium areas only. These instruments require special uranium probes which are distinguished by the words "URANIUM USE ONLY" stamped in green ink on the Efficiency Tag and on the screen.*

- 5.3 Notify Radiological Operations Foreman whenever finding a Ludlum Model 12-1A instrument or probe which is incorrect for the given area.
- 5.4 Radiation Protection personnel are permitted to replace defective batteries in the Model 12-1A and Model 31 survey instruments. RPT personnel are also permitted to replace the probe and cable of the Model 12-1A and Model 31 survey instruments. All other instrument servicing shall be referred to Radiation Instrumentation.
- 5.5 Probe serial numbers and instrument serial numbers must be recorded on the Performance Test Logs.

92-PCN-0088

94-DMR-000893

- 5.6 All pen and ink changes to documents generated by this instruction shall be done in black ink. Inappropriate items shall be lined out and initialed.

6. INSTRUCTIONS

- 6.1 All Ludlum Model 12-1A and Model 31 survey instruments shall be performance tested daily while in use.
- 6.2 The calibration tag for each instrument to be used or tested shall be visually checked to ensure the due date of calibration has not expired.
- 6.3 A performance test shall be performed before each day of instrument use, following the operational use period, and following replacement of batteries.
- 6.3.1 A battery check shall be conducted before each intermittent use of an instrument. Set the Selector switch to the BATTERY position. If the batteries are satisfactory, the meter needle will come to rest over the region of the meter scale area marked BAT TEST.
- If BAT TEST indicates low batteries, replace the batteries, and repeat the above tests. If the test indicated the batteries are still low the instrument shall be tagged with RF-47200 (Attachment 9.3) and returned to Radiation Instrumentation.
  - For the Model 12-1A High Voltage (HV) check (BAT TEST OK) the Selector switch shall be reset to the X1000 scale and the HV test button depressed. The meter shall read between 1.7 and 1.9 on the bottom