

SAFETY CONCERN NUMBER	SUBJECT	INITIATED BY DATE	SUPERVISOR DATE OF ANSWER	DATE REC'D BY COMM. ASSIGNED TO	COMMENTS	SETTLEMENT DATE	METHOD 1, 2, 3
85-155	Bldg. 444 - Coolant needs changing.	[REDACTED] 9/18/85	R. Hilbig 9/27/85	11/5/85 S. Nazzise C. Noble		11/19/85	2
85-156	Bldg. 444 - Coolant needs changing.	[REDACTED] 9/18/85	" " " "	" " " "		11/19/85	2
85-157	Bldg. 444 - Coolant needs changing.	[REDACTED] 9/18/85	" " " "	" " " "		11/19/85	2
85-158	Bldg. 444 - Coolant needs changing.	[REDACTED] 9/18/85	" " " "	" " " "		11/19/85	2
85-159	Bldg. 444 - Coolant needs changing.	[REDACTED] 9/18/85	" " " "	" " " "		11/19/85	2
85-160 ✓	Bldg. 776 - part being transported not bagged or labeled properly.	[REDACTED] 10/22/85	M. Reed 10/22/85	11/8/85 Scruggs Chanda		3/7/86	
85-161 ✓	Bldg. 883 - Decon of badges	[REDACTED] 10/30	G. Lathen 10/30/85	11/11/85 Scruggs Baker			
35-162 *	Bldg. 991 - Warehouse personnel driving fork trucks in unsafe manner.	[REDACTED] 10/17/85	E. Kirk 10/17/85	11/11/85 G. Overholt C. Trump	Resolved		
35-163	Bldg. 771 - Pblms with an RV.	[REDACTED] 10/9/85	D. Cox C. Russell 10/23/85	11/5/85 J. Scruggs F. Baker			
35-164 *	Bldg. 123 - need for sand barrel - north side.	[REDACTED] 10/9	W. Goode 10/9	11/15/85 Overholt Noble		11/18/85	2