

SAFETY CONCERN	SUBJECT	INITIATED BY DATE	SUPERVISOR DATE OF ANSWER	DATE REC'D BY COMM. ASSIGNED BY	COMMENTS	SETTLEMENT DATE	METHOD 1, 2, 3
* 86-108	BLDG. 771 -	[REDACTED] 4/23/86	S. DEWITT 5/8/86		CLOSED OUT	5/8/86	
- * 86-108	BLDG. 444 -	[REDACTED] 4/29/86	NORTON 5/6/86		CLOSED OUT	5/12/86	
- 86-110	BLDG. 444 - VISITORS & CONTRACTORS NOT FOLLOWING SAFETY REGULATIONS.	[REDACTED] 5/13/86	H. BRYAN 5/16/86	J. CASTRO A. HAGEN 5/20/86	CLOSED OUT	7/7/86	
- 86-111	BLDG. 771 - LACK OF MONITORS FOR SURVEYS.	[REDACTED] 5/1/86	J. RAY 5/6/86	J. SCRUGGS R. CHANDA 5/20/86	CLOSED OUT	8/27/86	
- 86-112	BLDG. 771 - FILTER CHANGE & TANK INSPECTIONS.	[REDACTED] 5/9/86	J. RAY 5/13/86	N. JAMES P. KING 5/20/86	CLOSED OUT	8/27/86	
- 86-113	BLDG. 559 - HOUSE VACUUM SYSTEM MAKING LOUD NOISES.	[REDACTED] 5/6/86	H. PITTS 5/12/86	J. CASTRO A. HAGEN 5/20/86	CLOSED OUT	6/19/86	
- 86-114	BLDG. 771 - AUGER NEEDS TO BE ADJUSTED.	[REDACTED] 4/30/86	S. DEWITT 5/13/86	J. CASTRO R. CHANDA 5/20/86	CLOSED OUT		
- 86-115	BLDG. 776 - MOLTEN SALT CREW HAS HIGH GAMMA RADIATION	[REDACTED] 4/30/86	W. DAVIS 5/8/86	G. OVERHOLT P. KING 5/20/86	CLOSED OUT	6/20/86	
- 86-116	BLDG. 881 - LAB. RM. 137 WEARING IMPROPER CLOTHING AROUND URANIUM CHIPS.	[REDACTED] 4/30/86	R. REISCHICK 5/6/86	J. CASTRO P. KING 5/22/86			