IND	MATTLE Gertrage
Guter 80 port High	DISTRIBUTION
	International HEALTH PHYSICS Orig.
7-70 -7 - ROCKY FLA	TS PLANT AREA SUPT
REPORT # _779-07-03 RADIATION MONI	
INCIDENT	BODY COUNTER N/A
DATE 07/10/85 POSSIBLE INHALAT	
TIME OF OCCUR. 1 4 4 D PROCEDURE VIOLA	TION X D.O.E. J. STEARNS
	IMMED. SUPER) NAVRATIL
RADIATION MONITORING DESCRIPTION OF F	IND. SAFETY
ROOM 133 GLOVE BOX # 956 OTHER	_ GLOVE # FILE _ 707 RM
INSTRUMENT WORKING ? SAAM #	SAAM C/M OTHER J. LEIGH
	SKIN CONTAMINATION RESP. BODY BODY COUNT
PERSONNEL INVOLVI	LEVELS WORN? COUNT? RESULTS
NAMENO	
NAMENO	
NAMENO	
WORKING THRU GLOVES IN I	DRY BOX WITH PERSONAL
CLOTHING ON, WAS WEARING A SMOCK	
Contract and, comp coopies	of The Shook
	1
A 12.	A A
V. algucia 508453	Malachen 506561
MONITOR'S SIGNATURE EMPLOYEE #	RADIATION MONITORING SUPERVISOR EMPLOYEE #
INVESTIGATION REQUIRED YES NO BY: BY: BY: THIS FORM TO BE FILLED OUT AND RETURNED WITHIN 24 HOURS TO RADIATION MONITORING SUPERVISION	
RESPONSIBLE SUPERVISOR'S FINDINGS An experiment, being set up by a new engineer, was being	
supervised by the end of	
shift so briefly assisted the engineer by passing along in the glove box, a few	
items to be weighed. He had a smock on and was wearing surgeons gloves.	
·	
CORRECTIVE ACTION: The action was well intentioned but a violation of the rules. The	
CORRECTIVE ACTION: The action was well intentioned but a violation of the rules. The obvious corrective action is to eliminate the occurence.	
othing when working in the gloves in the future.	
RESPONSIBLE SUPERVISOR SIGNATURE James D. Nauratet EMPLOYEE # 504435 DATE 7-23-85	
RESPONSIBLE SUPERVISOR SIGNATURE James D.	harratet_EMPLOYEE # 504435_DATE 7-23-85
RESPONSIBLE SUPERVISOR SIGNATURE famer D. Total Man Hours	Cost of Materials