

# VERIFICATION FORM

PASSED  FAILED

Safety Concern: 00-089  
Corresponding PATS ID:

Date All Actions Reported Complete: 11/28/2000

**Verification Results:** Completed

The Action Plan Addresses the Intent of the Resolution Letter?  Yes  No  N/A

**Findings: All corrective actions identified have been implemented. The SAAM was re-energized and the cut area was contained to allow the workers to remove any contamination.**

**Comments:**

---

**Verified By:**

*P.W. Dooley* 11/29/00  
P.W. Dooley, Union Representative Date

**Approved By:**

\_\_\_\_\_  
B.T. Carr, Union Co-Chair Date

\_\_\_\_\_  
S. D. Chestnut, Company Representative Date

\_\_\_\_\_  
M. P. Giacomini, Company Co-Chair Date

Distribution:  
PATS, T130G  
B.T. Carr, T690N  
S. D. Chestnut, T452B  
Company File, T117A  
Union File, T690N



# JOINT COMPANY-UNION SAFETY COMMITTEE



November 30, 2000

TO: [REDACTED]  
B771 RAD SAFETY  
Building 771  
Ext. [REDACTED]

FROM: M. P. Giacomini / B. T. Carr  
Joint Company/Union Safety Committee  
Building T117A / Building T690N  
Ext. 7620 / Ext. 5298

**SUBJECT: RECEIPT OF SAFETY CONCERN: 2000-089 - LACK OF  
CONTAINMENT ON BAG CUT**

The Joint Company/Union Safety Committee (JCUSC) has received your safety concern. Your response states that you are satisfied with the supervisor's answer.

The JCUSC considers this concern adequately addressed and closed. Changes to this agreement cannot be made without concurrence by the JCUSC. Thank you for your participation in the safety program. If you have any further questions or problems regarding this concern, please feel free to contact the JCUSC.

cc:

D. M. Boone, 771  
J. M. Brooks, 771, 771CP POC  
S. D. Chestnut, T117A  
Company File, T117A


P. W. Dooley, 690TG  
PATS, T130G  
R. J. Santangelo Jr, 771  
Union File, T690N

Union File

Local 8031

Building

**T690N**



# JOINT COMPANY/UNION SAFETY COMMITTEE CONCERN FORM

Case Number

00-089

This Form May Be Used By All RFETS Employees  
(NOTE: All lines MUST be completed)

Employee Name [Redacted] Employee Number [Redacted]  
Last Name, and Middle Initial

Employee Company (Matrix) K-H Department RAD OPS

Job Title RCT Bldg. 771 Phone [Redacted] Shift DAY

Supervisor DARREN BOONE Supv Ext 2751  
Print Last Name, First Name, and Middle Initial

I have previously discussed Concern with Supervision:  Yes  No

Location of Concern 771 ROOM 114 Safety Concern PROPER CONTAINMENT WAS NOT BEING USED TO CONTROL THE CUT BEING MADE ON BLOWBOX 8E. ALSO A ROOM SAAM WAS UNPLUGGED TO PERFORM THIS EVOLUTION. A STOP WORK ON THIS JOB HAS BEEN ISSUED.

Recommendation PUT ROOM SAAM BACK IN SERVICE FOR THIS EVOLUTION AND MAKE THE CUT INSIDE OF CONTAINMENT.

Employee Signature [Redacted] (Additional Space On Back) Date 11-15-00

Steward SANTANGELO ROBERT J Signature [Signature] Date 11-15-00  
Print Last Name, First Name, and Middle Initial If Applicable

Supervisor Response Within 5 Working Days (attach all pertinent documentation) THE SAAM WAS RE-ENERGIZED AND THE CUT AREA WAS CONTAINED TO ALLOW THE WORKERS TO BE REMOVED FROM POTENTIAL CONTAMINATION. AN AGREEMENT WAS REACHED BETWEEN ALL PARTIES INVOLVED TO RE-COMMENCE WORK  
(Additional Space On Back)

I have discussed above response with concerned employee [Signature] Date 11-28-00  
Supervisor Signature

Manager Boone, Darren M Ext 2751 Signature [Signature] Date 11-28-00  
Print Last Name, First Name, and Middle Initial

Satisfied with response  Not satisfied with response  Give brief reason if not satisfied:

Employee Signature [Redacted] Date 11-28-00

Assigned to:

Union Doolby Date 11/29/00

Company \_\_\_\_\_ Date \_\_\_\_\_

